

## GENERAL INFORMATION

### Client & Site Information:

**Inspection Date:**  
March 13, 2012.

**Inspection Time:**  
09:30 AM.

**Client:**  
Ms Mary Brown

**Inspection Site:**  
456 Castle Avenue  
Sharpsburg, GA 30277

### People Present:

Homeowner.  
Client's sister-in-law  
Client's Realtor.

### Building Characteristics:

**Estimated Age:**  
1989.

**Building Style & Type:**  
1 family.

**Stories:**  
2

**Space Below Grade:**  
Finished Basement.

**Water Source:**  
Public.

**Sewage Disposal:**  
Public.

**Utilities Status:**  
All utilities on.

### Climatic Conditions:

**Weather:**  
Overcast.

**Soil Conditions:**  
Very wet.

**Outside Temperature (F):**  
60-70.

### REPORT LIMITATIONS

This report is intended only as a general guide to help the client make his own evaluation of the overall condition of the home, and is not intended to reflect the value of the premises, nor make any representation as to the advisability of purchase. The report expresses the personal opinions of the inspector, based upon his visual impressions of the conditions that existed at the time of the inspection only. The inspection and report are not intended to be technically exhaustive, or to imply that every component was inspected, or that every possible defect was discovered. No disassembly of equipment, opening of walls, moving of furniture, appliances or stored items, or excavation was performed. All components and conditions which by the nature of their location are concealed, camouflaged or difficult to inspect are excluded from the report. The inspection is performed in compliance with generally accepted standard of practice, a copy of which is available upon request.

Systems and conditions which are not within the scope of the inspection include, but are not limited to: formaldehyde, lead paint, asbestos, toxic or flammable materials, and other environmental hazards; pest infestation, playground equipment, efficiency measurement of insulation or heating and cooling equipment, internal or underground drainage or plumbing, any systems which are shut down or otherwise secured; water wells (water quality and quantity) zoning ordinances; intercoms; security systems; heat sensors; cosmetics or building code conformity. Any general comments about these systems and conditions are informational only and do not represent an inspection.

The inspection report should not be construed as a compliance inspection of any governmental or non governmental codes or regulations. The report is not intended to be a warranty or guarantee of the present or future adequacy or performance of the structure, its systems, or their component parts. This report does not constitute any express or implied warranty of merchantability or fitness for use regarding the condition of the property and it should not be relied upon as such. Any opinions expressed regarding adequacy, capacity, or expected life of components are general estimates based on information about similar components and occasional wide variations are to be expected between such estimates and actual experience.

We certify that our inspectors have no interest, present or contemplated, in this property or its improvement and no involvement with tradespeople or benefits derived from any sales or improvements. To the best of our knowledge and