
BASEMENT

ASEMENT:	
6.1 ACCESSIBILITY:	Basement is fully accessible, Basement is finished, Stairs an handrail serviceable.
6.2 WALLS - TYPE:	Poured concrete.
6.3 CONDITION:	Appears serviceable.
6.4 BEAMS:	Appears serviceable, Beams were not fully visible due to finishe areas of basement.
6.5 FLOOR JOISTS:	Appear serviceable, The floor joists were not fully visible due finished areas of basement.
6.6 BASEMENT FLOOR:	Appears serviceable.
6.7 COMMENTS:	The basement was dry at the time of inspection and moisture meter readings taken at the perimeter indicated normal moisturelevels. Note: Long Island has high water tables and ferocion "Nor'easter" storms. It is inevitable that at some point we will have wet basements and wet crawl spaces.

Interior Dimensions



Measurements Are Approximate